



Curve charts

3 SQF-2



TM02 2426 4311


3 SQF-3



TM03 3930 4311


Note: Max. P1 (W) shown on curve represents max. motor RPM.

6 SQF-2



TM02 2427 4311


6 SQF-3



TM02 4648 4711


Note: Max. P1 (W) shown on curve represents max. motor RPM.

11 SQF-2



TM02 2428 4311


16 SQF-10



TM03 3931 4311


Note: Max. P1 (W) shown on curve represents max. motor RPM.

25 SQF-3



TM02 2429 4311


25 SQF-7



TM02 2430 4311


Note: Max. P1 (W) shown on curve represents max. motor RPM.

40 SQF-3



TM02 2431 4311


40 SQF-5



TM03 3932 4311

Note: Max. P1 (W) shown on curve represents max. motor RPM.

60 SQF-3



Note: Max. P1 (W) shown on curve represents max. motor RPM.

TM03 3933 4311